

ARRIVAL ROUTE DESCRIPTION

COLNS TRANSITION (COLNS.BRUSH4): From over COLNS on HNN R-090 to HNN VORTAC, then on HNN R-254 to BRUSH. Thence. . . .

HENDERSON TRANSITION (HNN.BRUSH4): From over HNN VORTAC on HNN R-254 to BRUSH. Thence. . . .

. . . .from over BRUSH on CVG R-127 to CVG VORTAC. Expect vectors to final approach course after GAVNN.

LOST COMMUNICATIONS

In the event of lost communications:

For LUK: At CVG VORTAC, proceed on V5 to WUSPU and hold, maintain 4000.

For I69: At CVG VORTAC, proceed to SPORTYS (PWF) maintain 4000 until SPORTYS (PWF).

For K62: At CVG VORTAC proceed on V517 to FLM VOR/DME, maintain 3000 until FLM VOR/DME.

SE-1, 16 JUL 2020 to 13 AUG 2020

SE-1, 16 JUL 2020 to 13 AUG 2020